














SC 55W




English
עברית

1
12



2**3****4****5**

6**7****8****9**

10**11****12**

SC 55W

en	Original operating instructions	1
he	הוראות הפעלה מקוריות	12

1 Information about the documentation

1.1 About this documentation

- Read this documentation before initial operation or use. This is a prerequisite for safe, trouble-free handling and use of the product.
- Observe the safety instructions and warnings in this documentation and on the product.
- Always keep the operating instructions with the product and make sure that the operating instructions are with the product when it is given to other persons.

1.2 Explanation of symbols used

1.2.1 Warnings

Warnings alert persons to hazards that occur when handling or using the product. The following signal words are used:


DANGER !

- ▶ Draws attention to imminent danger that will lead to serious personal injury or fatality.


WARNING !

- ▶ Draws attention to a potential threat of danger that can lead to serious injury or fatality.


CAUTION !

- ▶ Draws attention to a potentially dangerous situation that could lead to slight personal injury or damage to the equipment or other property.

1.2.2 Symbols in the documentation

The following symbols are used in this document:

	Read the operating instructions before use.
	Instructions for use and other useful information
	Dealing with recyclable materials
	Do not dispose of electric equipment and batteries as household waste

1.2.3 Symbols in the illustrations

The following symbols are used in illustrations:

2	These numbers refer to the corresponding illustrations found at the beginning of these operating instructions
3	The numbering reflects the sequence of operations shown in the illustrations and may deviate from the steps described in the text
(11)	Item reference numbers are used in the overview illustrations and refer to the numbers used in the product overview section
!	This symbol is intended to draw special attention to certain points when handling the product.

1.3 Product-dependent symbols

1.3.1 Symbols on the product

The following symbols can be used on the product:



2112861

	Wireless data transfer
n_0	Rated speed under no load
	Protection class II (double-insulated)
	Saw blade

1.4 Product information

HILTI products are designed for professional users and only trained, authorized personnel are permitted to operate, service and maintain the products. This personnel must be specifically informed about the possible hazards. The product and its ancillary equipment can present hazards if used incorrectly by untrained personnel or if used not in accordance with the intended use.

The type designation and serial number are printed on the rating plate.

- Write down the serial number in the table below. You will be required to state the product details when contacting Hilti Service or your local Hilti organization to inquire about the product.

Product information

Circular saw	SC 55W
Generation	01
Serial no.	

1.5 Declaration of conformity

We declare, on our sole responsibility, that the product described here complies with the applicable directives and standards. A copy of the declaration of conformity can be found at the end of this documentation.

The technical documentation is filed here:

Hilti Entwicklungsgesellschaft mbH | Tool Certification | Hiltistrasse 6 | D-86916 Kaufering, Germany

2 Safety

2.1 General power tool safety warnings

⚠ WARNING Read all safety warnings, instructions, illustrations and specifications provided with this power tool. Failure to follow all instructions listed below may result in electric shock, fire and/or serious injury.

Save all warnings and instructions for future reference.

The term "power tool" in the warnings refers to your mains-operated (corded) power tool or battery-operated (cordless) power tool.

Work area safety

- Keep work area clean and well lit.** Cluttered or dark areas invite accidents.
- Do not operate power tools in explosive atmospheres, such as in the presence of flammable liquids, gases or dust.** Power tools create sparks which may ignite the dust or fumes.
- Keep children and bystanders away while operating a power tool.** Distractions can cause you to lose control.

Electrical safety

- Power tool plugs must match the outlet. Never modify the plug in any way. Do not use any adapter plugs with earthed (grounded) power tools.** Unmodified plugs and matching outlets will reduce risk of electric shock.
- Avoid body contact with earthed or grounded surfaces, such as pipes, radiators, ranges and refrigerators.** There is an increased risk of electric shock if your body is earthed or grounded.
- Do not expose power tools to rain or wet conditions.** Water entering a power tool will increase the risk of electric shock.
- Do not abuse the cord.** Never use the cord for carrying, pulling or unplugging the power tool. Keep cord away from heat, oil, sharp edges or moving parts. Damaged or entangled cords increase the risk of electric shock.
- When operating a power tool outdoors, use an extension cord suitable for outdoor use.** Use of a cord suitable for outdoor use reduces the risk of electric shock.



- ▶ If operating a power tool in a damp location is unavoidable, use a residual current device (RCD) protected supply. Use of an RCD reduces the risk of electric shock.

Personal safety

- ▶ Stay alert, watch what you are doing and use common sense when operating a power tool. Do not use a power tool while you are tired or under the influence of drugs, alcohol or medication. A moment of inattention while operating power tools may result in serious personal injury.
- ▶ Use personal protective equipment. Always wear eye protection. Protective equipment such as a dust mask, non-skid safety shoes, hard hat or hearing protection used for appropriate conditions will reduce personal injuries.
- ▶ Prevent unintentional starting. Ensure the switch is in the off-position before connecting to power source and/or battery pack, picking up or carrying the tool. Carrying power tools with your finger on the switch or energising power tools that have the switch on invites accidents.
- ▶ Remove any adjusting key or wrench before turning the power tool on. A wrench or a key left attached to a rotating part of the power tool may result in personal injury.
- ▶ Do not overreach. Keep proper footing and balance at all times. This enables better control of the power tool in unexpected situations.
- ▶ Dress properly. Do not wear loose clothing or jewellery. Keep your hair and clothing away from moving parts. Loose clothes, jewellery or long hair can be caught in moving parts.
- ▶ If devices are provided for the connection of dust extraction and collection facilities, ensure these are connected and properly used. Use of dust collection can reduce dust-related hazards.
- ▶ Do not let familiarity gained from frequent use of tools allow you to become complacent and ignore tool safety principles. A careless action can cause severe injury within a fraction of a second.

Power tool use and care

- ▶ Do not force the power tool. Use the correct power tool for your application. The correct power tool will do the job better and safer at the rate for which it was designed.
- ▶ Do not use the power tool if the switch does not turn it on and off. Any power tool that cannot be controlled with the switch is dangerous and must be repaired.
- ▶ Disconnect the plug from the power source and/or remove the battery pack, if detachable, from the power tool before making any adjustments, changing accessories, or storing power tools. Such preventive safety measures reduce the risk of starting the power tool accidentally.
- ▶ Store idle power tools out of the reach of children and do not allow persons unfamiliar with the power tool or these instructions to operate the power tool. Power tools are dangerous in the hands of untrained users.
- ▶ Maintain power tools and accessories. Check for misalignment or binding of moving parts, breakage of parts and any other condition that may affect the power tool's operation. If damaged, have the power tool repaired before use. Many accidents are caused by poorly maintained power tools.
- ▶ Keep cutting tools sharp and clean. Properly maintained cutting tools with sharp cutting edges are less likely to bind and are easier to control.
- ▶ Use the power tool, accessories and tool bits etc. in accordance with these instructions, taking into account the working conditions and the work to be performed. Use of the power tool for operations different from those intended could result in a hazardous situation.
- ▶ Keep handles and grasping surfaces dry, clean and free from oil and grease. Slippery handles and grasping surfaces do not allow for safe handling and control of the tool in unexpected situations.

Service

- ▶ Have your power tool serviced by a qualified repair person using only identical replacement parts. This will ensure that the safety of the power tool is maintained.

2.2 Safety instructions for all saws

Cutting procedures

- ▶ **DANGER:** Keep hands away from cutting area and the blade. Keep your second hand on auxiliary handle or motor housing. If both hands are holding the saw, they cannot be cut by the blade.
- ▶ Do not reach underneath the workpiece. The guard cannot protect you from the blade below the workpiece.
- ▶ Adjust the cutting depth to the thickness of the workpiece. Less than a full tooth of the blade teeth should be visible below the workpiece.
- ▶ Never hold the workpiece in your hands or across your leg while cutting. Secure the workpiece to a stable platform. It is important to support the work properly to minimise body exposure, blade binding, or loss of control.



- ▶ Hold the power tool by insulated gripping surfaces, when performing an operation where the cutting tool may contact hidden wiring or its own cord. Contact with a "live" wire will also make exposed metal parts of the power tool "live" and could give the operator an electric shock.
- ▶ When ripping, always use a rip fence or straight edge guide. This improves the accuracy of cut and reduces the chance of blade binding.
- ▶ Always use blades with correct size and shape (diamond versus round) of arbour holes. Blades that do not match the mounting hardware of the saw will run off-centre, causing loss of control.
- ▶ Never use damaged or incorrect blade washers or bolt. The blade washers and bolt were specially designed for your saw, for optimum performance and safety of operation.

Kickback causes and related warnings

- Kickback is a sudden reaction to a pinched, jammed or misaligned saw blade, causing an uncontrolled saw to lift up and out of the workpiece toward the operator;
- when the blade is pinched or jammed tightly by the kerf closing down, the blade stalls and the motor reaction drives the unit rapidly back toward the operator;
- if the blade becomes twisted or misaligned in the cut, the teeth at the back edge of the blade can dig into the top surface of the wood causing the blade to climb out of the kerf and jump back toward the operator.

Kickback is the result of saw misuse and/or incorrect operating procedures or conditions and can be avoided by taking proper precautions as given below.

- ▶ **Maintain a firm grip with both hands on the saw and position your arms to resist kickback forces.** Position your body to either side of the blade, but not in line with the blade. Kickback could cause the saw to jump backwards, but kickback forces can be controlled by the operator, if proper precautions are taken.
- ▶ **When blade is binding, or when interrupting a cut for any reason, release the trigger and hold the saw motionless in the material until the blade comes to a complete stop. Never attempt to remove the saw from the work or pull the saw backward while the blade is in motion or kickback may occur.** Investigate and take corrective actions to eliminate the cause of blade binding.
- ▶ **When restarting a saw in the workpiece, centre the saw blade in the kerf so that the saw teeth are not engaged into the material.** If a saw blade binds, it may walk up or kickback from the workpiece as the saw is restarted.
- ▶ **Support large panels to minimise the risk of blade pinching and kickback.** Large panels tend to sag under their own weight. Supports must be placed under the panel on both sides, near the line of cut and near the edge of the panel.
- ▶ **Do not use dull or damaged blades.** Unsharpened or improperly set blades produce narrow kerf causing excessive friction, blade binding and kickback.
- ▶ **Blade depth and bevel adjusting locking levers must be tight and secure before making the cut.** If blade adjustment shifts while cutting, it may cause binding and kickback.
- ▶ **Use extra caution when sawing into existing walls or other blind areas.** The protruding blade may cut objects that can cause kickback.

Lower guard function

- ▶ **Check the lower guard for proper closing before each use. Do not operate the saw if the lower guard does not move freely and close instantly. Never clamp or tie the lower guard into the open position.** If the saw is accidentally dropped, the lower guard may be bent. Raise the lower guard with the retracting handle and make sure it moves freely and does not touch the blade or any other part, in all angles and depths of cut.
- ▶ **Check the operation of the guard return spring.** If the guard and the spring are not operating properly, they must be serviced before use. Lower guard may operate sluggishly due to damaged parts, gummy deposits, or a build-up of debris.
- ▶ **The lower guard may be retracted manually only for special cuts such as "plunge cuts" and "compound cuts".** Raise the lower guard by the retracting handle and as soon as the blade enters the material, the lower guard must be released. For all other sawing, the lower guard should operate automatically.
- ▶ **Always observe that the lower guard is covering the blade before placing the saw down on bench or floor.** An unprotected, coasting blade will cause the saw to walk backwards, cutting whatever is in its path. Be aware of the time it takes for the blade to stop after switch is released.




2.3 Additional safety instructions for circular saws

- Bring the saw blade into contact with the workpiece only when the circular saw is switched on.
- The path of the saw must be free of obstructions above and below the workpiece. Do not saw into screws, nails or similar objects.
- Never work overhead with a circular saw.
- Never attempt to brake the saw blade by applying lateral pressure.
- Avoid overheating the tips of the saw blade teeth.
- When cutting plastic, avoid melting the plastic.
- Always use a saw blade that is suitable for the material you are going to saw.
- Use only saw blades recommended by Hilti that comply with the EN 847-1 standard.

3 Description

3.1 Product overview 1



- | | |
|---|--|
| ① | Single-arm fence |
| ② | Cutting angle setting |
| ③ | Spindle lock button |
| ④ | Auxiliary grip |
| ⑤ | On/off switch |
| ⑥ | Switch-on interlock release button |
| ⑦ | Grip |
| ⑧ | Electric supply cable |
| ⑨ | Clamping lever for cutting depth adjustment |
| ⑩ | Hex key |
| ⑪ | Small base plate |
| ⑫ | LED illumination |
| ⑬ | Front clamping lever for the fence |
| ⑭ | Clamping lever for cutting angle adjustment |
| ⑮ | Cutting depth scale |
| ⑯ | Hose connector (vacuum cleaner) |
| ⑰ | Guard |
| ⑱ | Pivoting guard operating lever |
| ⑲ | Rear clamping lever for the fence (only with large base plate) |
| ⑳ | Pivoting guard |
| ㉑ | Arbor |
| ㉒ | Direction-of-rotation arrow |
| ㉓ | Twin-arm fence |
| ㉔ | 0° cutting line indicator |
| ㉕ | 45° cutting line indicator |
| ㉖ | Cutting angle scale |
| ㉗ | Large base plate |
| ㉘ | Clamping screw |
| ㉙ | Clamping flange |
| ㉚ | Mounting flange |
| ㉛ | 0° indicator on the base plate |
| ㉜ | 1°- 50° indicator on the base plate |

3.2 Overview of the guide rail adapter 2

- | | | | |
|---|---------------------|---|-------------------|
| ㉟ | Rear retaining lug | ㉞ | 0° indicator |
| ㉟ | Front retaining lug | ㉞ | 1°- 50° indicator |



2112861

English

5

3.3 Intended use

The product described is a circular saw. It is designed for cutting wood or wood-like materials, plastics, gypsum plasterboard, gypsum fiberboard and composite materials, up to a cutting depth of 55 mm, and for miter cuts at angles up to 50°.

3.3.1 Possible misuse

Do not use saw blades not compliant with the technical data and do not use cutting discs, abrasive wheels or saw blades made of highly alloyed high speed steel (HSS steel). Do not use this power tool to saw metal.

3.4 Items supplied

Circular saw, saw blade, hex key, rip fence, operating instructions.

 To help ensure safe and reliable operation, use only genuine Hilti spare parts and consumables. Spare parts, consumables and accessories approved by Hilti for use with the product can be found at your local **Hilti Store** or online at: www.hilti.group

4 Technical data

4.1 Technical data

 For rated voltage, frequency, current and input power, please refer to the country-specific type identification plate.

If the device is powered by a generator or transformer, the generator or transformer's power output must be at least twice the rated input power shown on the rating plate of the device. The operating voltage of the transformer or generator must always be within +5 % and -15 % of the rated voltage of the device.

Weight, small base plate	4.5 kg
Weight, large base plate	4.7 kg
Saw blade diameter	160 mm ... 165 mm
Saw blade disc thickness	1.1 mm ... 1.5 mm
Saw blade arbor size	20 mm
Cutting depth at 0°	0 mm ... 55 mm
Cutting depth at 45°	0 mm ... 41 mm
Cutting depth at 50°	0 mm ... 37 mm
No-load speed	5,500 /min

4.2 Noise information and vibration values in accordance with EN 62841

The sound pressure and vibration values given in these instructions were measured in accordance with a standardized test and can be used to compare one power tool with another. They can also be used for a preliminary assessment of exposure.

The data given represent the main applications of the power tool. However, if the power tool is used for different applications, with different accessory tools, or is poorly maintained, the data can vary. This can significantly increase exposure over the total working period.

An accurate estimation of exposure should also take into account the times when the tool is switched off, or when it is running but not actually being used for a job. This can significantly reduce exposure over the total working period.

Identify additional safety measures to protect the operator from the effects of noise and/or vibration, for example: maintaining the power tool and accessory tools, keeping the hands warm, organization of work patterns.

Noise information

Sound power level (L_{WA})	101 dB(A)
Sound pressure level (L_{pa})	90 dB(A)
Uncertainty	3 dB(A)



Vibration information

	230 V	110 V
Triaxial vibration value when cutting wood (a_{th})	1.77 m/s ² (5.81 ft/s ²)	2.12 m/s ² (6.96 ft/s ²)
Uncertainty (K)	1.5 m/s ²	1.5 m/s ²

5 Operation**5.1 Removing the saw blade 3****⚠ WARNING**

Risk of burning injury. A hot accessory tool, clamping flange or clamping screw and the sharp edges of the saw blade present hazards.

- ▶ Wear protective gloves when changing saw blades.

1. Disconnect the supply cord plug from the power outlet.
2. Insert the hex key into the saw blade securing screw.
3. Press the drive spindle lock button and hold it in this position.
4. Turn the saw blade clamping screw with the hex key until the spindle lock button engages fully.
5. Release the clamping screw by turning the hex key in the direction of the direction-of-rotation arrow.
6. Remove the clamping screw from the outer clamping flange.
7. Open the pivoting guard by swinging it to the side and then remove the saw blade.



If necessary, the mounting flange can be removed for cleaning.

5.2 Install saw blade 4**⚠ CAUTION**

Risk of damage Unsuitable or incorrectly fitted saw blades may damage the saw.

- ▶ Only use blades which are suitable for this saw. Observe the direction-of-rotation arrow on the saw blade.
- ▶ Use only saw blades equipped with a rated maximum permissible speed that is at least as high as the maximum speed stated on the product.

1. Disconnect the supply cord plug from the power outlet.
2. Clean the mounting flange and the clamping flange.
3. Fit the outer clamping flange the right way round (i.e. facing the right direction).
4. Open the pivoting guard.
5. Fit the new saw blade.
6. Install the outer clamping flange the right way round.
7. Insert the clamping screw.
8. Insert the hex key into the saw blade clamping screw.
9. Secure the clamping flange with the clamping screw by turning it clockwise. At the same time, use one hand to hold down the arbor lock button.
10. Before using the power tool, check that the saw blade is correctly seated and tightened securely.

5.3 Adjusting the cutting depth 5

1. Disconnect the supply cord plug from the power outlet.
2. Release the cutting depth adjustment clamping lever.
3. Lift the circular saw in a scissoring movement and set the cutting depth.
 - ↳ The cutting depth is shown on the cutting depth scale.



For a clean-edged cut, set cutting depth to the thickness of the material plus 2 mm.

4. Secure the cutting depth adjustment clamping lever.



5.4 Setting the miter cut angle **6**

1. Disconnect the supply cord plug from the power outlet.
2. Release the cutting angle adjustment clamping lever.
3. Pivot the base plate to the desired miter cut angle.
 - ↳ The miter cutting angle is shown on the miter cut angle scale.
4. Tighten the cutting angle adjustment clamping lever.

5.5 Cutting line indicator

At the front edge of the base plate of the circular saw is a line indicator for straight cuts and miter cuts (0° and 45°). This permits accurate cutting at the desired miter angle. The edge of the line indicator corresponds to the inside of the saw blade. There is a cutting line indicator at the opening for the saw blade at the front end of the base plate.

5.5.1 Sawing along a line **7**



Secure the workpiece to prevent movement.

Position the workpiece so that the saw blade is free to rotate beneath it.

Check that the on/off switch on the product is in the "off" position.

Position the forward section of the circular saw's base plate on the workpiece but do not bring the blade into contact with the workpiece.

1. Switch on the circular saw.
2. Guide the circular saw along the cutting line on the workpiece at a suitable speed.

5.6 Sawing with the fence **8**

The single-arm fence can be used to make accurate cuts along the edge of a workpiece or to rip strips of equal width. The fence can be fitted on either side of the base plate.

The twin-arm fence can be used only with the large base plate

When installing the fence, make sure that it is installed right way round.

5.7 Sawing with the guide rail.

Sawing with the guide rail can reduce the risk of kickback.

5.7.1 Inserting into / removing from the guide rail adapter **9**



When using saws with a small base plate, please use a guide rail adapter that fits the guide rail.

1. Remove the fence, if one is fitted.
2. Fit the base plate into the rear retaining lugs of the guide rail adapter.
3. Bring the front edge of the base plate down fully into the guide rail adapter. The base plate must engage fully with the front retaining lug.
4. To remove, pull the front retaining lug forward slightly and remove the circular saw from the guide rail adapter.

5.7.2 Longitudinal cuts at 0° **10**

- Place the circular saw on the guide rail with the groove marked " 0° " on the rib on the rail.

5.7.3 Longitudinal cuts at angles up to 50° **11**

CAUTION

Risk of damage If the saw is engaged in the wrong groove, the saw blade will collide with the guide rail.

- Place the saw in the correct groove.

- Place the saw on the guide rail with the groove marked " $1^\circ - 50^\circ$ " on the rib on the rail.



5.7.4 Using the saw on the guide rail

- Secure the guide rail from below with two screw clamps.
- Position the circular saw on the guide rail a short distance from the starting point of the cut. Open the guard manually when making longitudinal cuts (ripping) at cutting angles of 20°- 50°.



The saw must be placed on the guide rail behind the workpiece.

Take care to ensure that the saw blade is not in contact with the workpiece.

- Switch on the circular saw.
- Push the saw at a steady speed across the workpiece.
 - At cutting angles under 20° the pivoting guard opens automatically when it makes contact with the lateral actuating edge.
 - It closes again automatically when the saw leaves the end of the guide rail.

5.8 Sawing with or without sawdust extraction

The circular saw has a connector that fits common types of vacuum cleaner hose with a diameter of 27 mm. A suitable adapter might be required for connecting the vacuum-cleaner hose to the circular saw.

If possible, always use a suitable mobile dust removal system for wood and wood and mineral materials.

If you are working without a sawdust extractor, turn the ejector so that the sawdust is directed away from you.



Always use a filter class P2 dust mask and always ensure adequate ventilation to help minimize exposure to dust.

6 Care and maintenance

6.1 Care and maintenance



WARNING

Electric shock hazard! Attempting care and maintenance with the supply cord connected to a power outlet can lead to severe injury and burns.

- Always unplug the supply cord before carrying out care and maintenance tasks.

Care

- Carefully remove any dirt that may be adhering to parts.
- Clean the air vents carefully with a dry brush.
- Use only a slightly damp cloth to clean the casing. Do not use cleaning agents containing silicone as these may attack the plastic parts.

Maintenance



WARNING

Danger of electric shock! Improper repairs to electrical components may lead to serious injuries including burns.

- Repairs to the electrical section of the tool or appliance may be carried out only by trained electrical specialists.
- Check all visible parts and controls for signs of damage at regular intervals and make sure that they all function correctly.
- Do not operate the product if signs of damage are found or if parts malfunction. Have it repaired immediately by **Hilti** Service.
- After cleaning and maintenance, fit all guards or protective devices and check that they function correctly.



To help ensure safe and reliable operation, use only genuine Hilti spare parts and consumables. Spare parts, consumables and accessories approved by Hilti for use with the product can be found at your local **Hilti Store** or online at: www.hilti.group.

6.2 Checks after cleaning and maintenance



After cleaning or maintenance, check that all safety devices are fitted and that they function faultlessly.



- To check the pivoting guard, open the guard fully by moving the guard operating lever.
 - ↳ The pivoting guard must close quickly and completely when the guard operating lever is released.

6.3 Cleaning the ejector



The saw blade must be removed during cleaning if necessary.

1. Disconnect the supply cord plug from the power outlet.
2. Remove the saw blade. → page 7
3. Clean the ejector.
4. Install the saw blade. → page 7
5. Check that moving parts are in full working order and do not jam and make sure there are no parts that are broken or damaged in such a way as to impair operation of the power tool.

6.4 Cleaning the guard

1. Remove the saw blade. → page 7
2. Clean the parts of the guard carefully with a dry brush.
3. Use a suitable tool to remove deposits or cuttings from the inside surfaces of the parts of the guard.
4. Install the saw blade. → page 7

7 Troubleshooting

Trouble or fault	Possible cause	Action to be taken
The power tool does not develop full power.	The extension cord is too long or its gauge is inadequate.	► Use an extension cord of an approved length and/or of adequate gauge.
	The voltage provided by the electric supply is too low.	► Connect the power tool to a different electric supply.
The power tool does not work.	Interruption in the electric supply.	► Plug in another power tool or appliance and check whether it works.
	The supply cord or plug is defective.	► Have the power cord or the plug checked by a trained electrical specialist, and if necessary replaced by Hilti service.
	The on / off switch is defective.	► Have the product repaired by Hilti Service.
	The carbon brushes are worn.	► Have the product repaired by Hilti Service.
No suction power or reduced suction power	The chip ejector channel is blocked.	► Clean the ejector. → page 10
The pivoting guard does not close.	Safety device is clogged.	► Clean the guard. → page 10
The power tool vibrates more than usual.	The saw blade is fitted incorrectly.	► Remove the saw blade and install it again correctly.

8 Disposal

Most of the materials from which **Hilti** tools and appliances are manufactured can be recycled. The materials must be correctly separated before they can be recycled. In many countries, your old tools, machines or appliances can be returned to **Hilti** for recycling. Ask **Hilti** Service or your **Hilti** representative for further information.



- Do not dispose of power tools, electronic equipment or batteries as household waste!



9 RoHS (Restriction of Hazardous Substances)

Click on the link to go to the table of hazardous substances: qr.hilti.com/r2937786.
There is a link to the RoHS table, in the form of a QR code, at the end of this document.

10 Manufacturer's warranty

- ▶ Please contact your local **Hilti** representative if you have questions about the warranty conditions.



1.1 על אזהות תיעוד זה

- קרא את הוראות הפעלה לפני השימוש הראשון. רק כך ניתן להבטיח בטוחה ונטולת תקלות.
- ציית להוראות הפעלה והאזהות שבתיעוד זה ולאלה המופיעות על המוצר.
- שמר את הוראות הפעלה תמיד בצדם למוצר, והקפד להעביר אותן לאדם שאליו אתה מעביר את המוצר.

1.2 הסבר הסימנים**1.2.1 אזהרות**

האזהרות מדרירות מפנוי סכנות בשימוש במוצר. במדיריך זה מופיעות מילוט המפתח הבאונות:



◀ מצינית סכנה מיידית, המוביל לפציעות גוף קשות או מוות.



◀ מצינית סכנה אפשרית, שיכולה להוביל לפציעות גוף קשות או מוות.



◀ מצינית מצב שעלול להיות מסוכן ולהוביל לפציעות או לנקדים לרכוש.

1.2.2 סמלים במסמך זה

הסמלים הבאים מופיעים בתיעוד זה:

	קבע את הוראות הפעלה לפני השימוש
	הנחיות לשימוש ו מידע שימושי נוספים
	טיפול נכון בחומרים למייחזר
	אין להשליך לפסולת הביתיית מכשירים חשמליים וסוללות

1.2.3 סמלים באירועים

הסמלים הבאים משמשים באירועים:

2	מספרים אלה מפנים לאיו המטאים בתחילת חוברת ההוראות
3	המספרים באירועים משקפים את רצף הפעולות, ו�� לשווים להיות שונים מרצף הפעולות המצוינות בטקסט
11	מספר הפרטים מופיעים באירוע סקירה ותואמים את המספרים בפרק סקירת המוצר
!	סימן זה אמור לעורר את תשומת לך הפוחדת בעת השימוש במוצר.

1.3 סמלים ספציפיים למוצר**1.3.1 סמלים על המוצר**

הסמלים הבאים עשויים להופיע על המוצר:

	תעבורה נתונים אלחוטית
	מהירות סרף נקובה
	דרוג הגנה II (בידוד כפול)



**1.4 פרט ה מוצר**

ה מוצרים של **HILTI** מיועדים למשתמש המתקצועי, ורק אנשי מורים, שעבורו ה כשרה מתאימה, רשאים לתפעל, יחדם ולתקין אותם. אגשיים אלה ויבטים למדו באופן מיוחד את הסכנות האפשריות, המוצר המתואר והעדות שלו עלולים להיות מוכנים נזק או נזקם שלא עברו ה כשרה מתאימה משתמשים בהם באופן לא מקצועי או כאשר משתמשים בהם שלא בהתאם ליעוד. שם הדגם והספורה הסידורי מציינים לעוזר הדקה.

שם הדגם והספורה הסידורי בטלבה הבאה. בכל פניה לנציגינו או למעבדת שירות יש לציין את נתוני המוצר.

נתוני המוצר

מס' עגל	SC 55W
دور	01
מס' סידורי	

1.5 הצהרת תאימות

אנו מזכירים באחריותנו הבלעדית כי המוצר המתואר כאן תואם את התקנות והתקנים התקפיים. בסוף תייעוד זה ישנו צילום של הצהרת התאימות. התיעוד הטכני שמור כאן:

Hilti Entwicklungsgesellschaft mbH | Zulassung Geräte | Hiltistraße 6 | 86916 Kaufering, Germany

2 בטיחות**2.1 הוראות בטיחות כלולות לכל שימוש חשמליים**

- ⚠ אזהרה קרא את כל הוראות הבטיחות, ההנחיות, האירוטים והנתונים הטכניים המצורפים לכל ה עבודה החשמלי. אי ציון להנחיות עלול להווביל להתחשמלו, לשופר ו/או לפיציעות קשות.
- שמור את הוראות הבטיחות וההנחיות לעין בעתיד.
- "לily בעודה חשמל" המשמש בהוראות הבטיחות מתייחס לכל עודה חשמליים המוחברים לרשת החשמל (עם כל חשמל) או לכל עודה חשמליים המופעלים באמצעות סוללה נטענת (לא כולל חשמל).
- ביטחונות במקום העבודה**
- שמור על אזור העבודה שלך נקי ודאג למתארה מספקת. חוסר סדר או תאזורו לקויה במקום העבודה עלולים לגרום לתאונות.
- אין להפעיל את כל ה עבודה החשמלי הבסביבה שקיים בה סכנת פיצוץ או שישנה בה נחלים, גידים או אבק דליקים.
- כל עודה חשמליים יוצרם ביצירות, עלולים להזכיר את האבק או האדים.
- הרחק לדים ואנשי אחרים מכל ה עבודה החשמלי במהלך השימוש בו. אם דעתך תוסח אתה עלול לאבד את השיליטה במכשיך.

ביטחונות בחשמל

- תקח החשמל של כל ה עבודה החשמלי חיש בהתאמים לשיקע החשמל. אסוט לשוכות בשום אופן את תקע החשמל. אל תשתמש בשקע מותאם ביחס עם כל עודה חשמליים הכלולים הגנת האורך. שימוש בתקעים חשמליים שלא עברו סיורי ושיקע מותאים מפחית את הסיכון להתחשמלות.
- מכע מגע של הגוף בשטחים מוארים כגון צינורות, גווים חימום, תנורים ומקררים. קיימת סכנה בגופה להתחשמלות כאשר הגוף שלך מוארך.
- הרחק כל עודה החשמליים מגשם או רטיבות. חידרת מים לכל ה עבודה החשמלי מגדילה את הסיכון להתחשמלות.
- אל תשתמש בכל החשמל למטרות שלא שנועדו לכך, לדוגמה: אל תירז כל עודה החשמלי באמצעותו הcabל ואל תנסה לבתך את התקע המשקע המחבר במושך מכחום, שמן, פינות חודת או מחלקים בערים. כבלים שכיווקן או שותהבו בחלקים אחרים מאייטים את הסיכון להתחשמלות.
- כאשר אתה עבד עם כל ה עבודה החשמלי בחוות, השתמש רק בכבל מאיריך המוצע לשימוש חיצוני. שימוש בכבל מאיריך המתאים לשימוש חיצוני מפחית את הסיכון להתחשמלות.
- אם לא ניתן להימנע משימוש בכל ה עבודה החשמלי בסביבה לחה, השתמש במקרה פחת. השימוש במקרה פחת מפחית את הסיכון להתחשמלות.

ביטחונות של אבכים

- היא עבוי, כדי לבה מה שאותה עשויה, ופעול בתובנה כאשר אתה עובד עם כל עודה חשמלי. אל תפעיל כל עודה חשמליים כשתאתה עירף או תחת השפעת סטם, אלכוהול או תרופות. די ברגע אחד של חוסר תשומת-לב בזמן השימוש בכל ה עבודה החשמלי כדי לגרום פיציעות קשות.
- לבש תמיד ציוד מגן וושפף מגן. לבש ציוד מגן אישי, כגון מסכת אבק, גיגון מונענות החולקה, קסדה מגן או מגני שמייה – בהתאם לסוג השימוש בכל ה עבודה החשמלי – מקטינה את הסיכון לפיציעות.



2112861

עברית

13

- מגע הפעלה בשוגג. וזה שכי העבודה החשמלי כבוי לפניו שאותה מחבר או לאספקת החשמל ואו לפניו שאותה מחבר את הסוללה ולפכו הרמותו. אל תחיכך את אצבעך על המותג בדופן שאותה נושא את המכשיר ואל תחבר אותו לאספקת החשמל כאשר הוא כופען, אחריה עלולות להיגרם תאונות.
- הרחק כל' כוכום או מפתחות ברגים לפני אותה מפעיל את כל' העבודה החשמלי. כל' עבודה או מפתחות הנמצאים בקורת חלקי מסתובבים עלילום לגורם פציעות.
- הימנע מפתחות דוג'ף לא בכנות. עוד בזופן יציב ושמור תמיד על שווי משקל. כך תוכל לשולט טוב יותר בכל' העבודה החשמלי במנועים לא צפויים.
- لبש בגדיים מותאיים. אל תלبس בגדים רחבים או ישיר אורך עוללים יהויטס בחולקים עליים. בגדים רופפים, תשיטים ושרוולים יונטו בהזניפס עליים.
- כאשר ניתן להתקין התקין שאיבת אבק ולכידה יש לוודא שהמוחברים לחשמל, ושלה הקפיד לשימוש בהם בכוונה. שימוש בהתקין שאיבת אבק מקטין את הסכנות הנכונות מהאבק.
- אל תהיי שאנן בנושאי בטיחות ואל תעלט מהוראות בטיחות של כל' עבודה חשמלי, גם אם שהשתמשה במכשיר פעמיים בזבוז ואותה מפיר אותו יטב. התהנחות רשלתי עלולה להוביל לפציעות קשות בתוך שכיות.
- שימוש וטיפול בכל' העבודה החשמלי**
- אל תפעיל מומנט רב מדי על המכשיר. השתמש בכל' העבודה החשמלי המתאים לעבודה שאתה מבצע. כל' העבודה החשמלי הממאים בטיחי לך עבודה טيبة ובווחה יותר ביחסם להפקה הנקבה.
 - אל תשמש בכל' העבודה אם המותג שלו אינו תקין. כל' עבודה חשמלי שלא ניתן עוד להפעיל או לכובץ אותו מהוות סכנה ויש תקנן.
 - נתק את תקע החשמל מהשקע ו/או הסר את הסוללה לפני אותה מבצע כוכונים במכשיר, מחליף כלים או לאחר מכן שאותה מפסיק לעבוד עם המכשיר. אמצעי זהירות זה מונע הפעלה בשוגג של כל' העבודה החשמלי.
 - שורר כל' עבודה חשמליים שאיים בשימוש הרוחק מושך ים של יולדים. אל תאפשר לאגושים שאיים יודעים כיצד להשתמש במכשיר או שלא קראו את ההוראות להשתמש במכשיר. כל' עבודה חשמליים הם מօסנים כאשר משתמשים בהם אנשי חסרי ניסיון.
 - טפל בכל' העבודה חשמליים ובאביזרים בהקפודה. בודק אם החלקים הנעים פועלים בזרחה נכונה ואינם בתקעים, אם ישם חלקיים שבורים או מוקלקלים המשבשים את הפעולה התקינה של כל' העבודה החשמלי. לפni השימוש במכשיר דאג לתיקון חלקיים לא תקינים. תאותות רבות גרגשו עקב תחזקה לוויה של כל' עבודה חשמליים.
 - שורר כל' החיתוך חדים ובקרים. כל' חיתוך מטופלים היבר, שהלביהם חדים ונקיים פחות וקלים יותר ל接触. השתמש בכל' העבודה החשמלי, באבדרים, בכל' העבודה הנוטפים וכן הלאה בהתאם להוראות אלה. התחשב בתנאי העבודה ובפעולה שעילך לבצע. שימוש בכל' העבודה החשמלי למטרות אחרות מאשר שלישון הוא מיניע על להיות מסוכן.
 - שורר על ידיות ואזרוי אחידה בקיים מללך משwon ומגריד. ידיות ואזרוי אחידה חלקיים אינם מאפשרים פעולה בטוחה ושילטה טובה בכל' העבודה החשמליים במנועים לא צפויים.
- שירות**
- דאג לתיקון כל' העבודה החשמלי שלך רק בידי טכניים מוסמכים, המשתמשים בחלקי חילוף מקוריים בלבד. כך תבטיח שמירה על בטיחות העבודה במכשיר.

2.2 הוראות בטיחות לכל' המסתורים

- תהליך חיתוך**
- ⚠ סכנתן של תשלוח זיידים לאזרום מססרו וללהב המoso. אחד בזיך השבניה בידית הנוספת או בbite המכוון. אם שטי' ייך' ייחסו במסו, הלהב לא יכול לפצוץ אותן.
- אל תחוך מתחת חלק שבעבודה. מגן הלהב אינו יכול להגן עליך מפני לך המoso מתחת חלק שבעבודה.
- התאם את עוקק החיתוך לעובי החלק שבעבודה. הלהב צריך לבלוט מתחת חלק שבעבודה גובה שנן מלאה. בשום אופן אל תחדק בזיך או ברולין את החלק שברצונך לסרר. תוך את החלק שברצונך למוקם איבר. חשב מודוד ליציב היבט את החלק שבעבודה כדי למדוע את הסיכון מגע בגוף, להיתקעות של להב המoso או לאיבוד השליטה במסו.
- כאשר אתה מבצע עבודות שבהן הכל' עלול לפחות פגוע בקווי חשמלי מוסתרים או בכבל החשמל של המכשיר החדק את כל' העבודה החשמלי ורק עלולה לגרום להיתקעות. מגעה בקווי המוליך חשמל תעביר זרם גם לחלקי המסתורים של כל' העבודה החשמלי ורק עלולה לגרום להיתקעות.
- בעת חיתוך לאורך החלק יש לשימוש תמייך במוליך. המוליך משפר את הדיק בחתום ומפחית את הסיכון להיתקעות להב המoso.
- השתמש תמיד בלחיבי מסור בגודל הנכון ובועל קדח מותאים (כגון בצתורה כוכב או עגול). להבי מסור שאימים מותאים לריכבי החיבור של המסור יסתובבו בזראה לא עוגלה ויגרמו לאבדון השילטה.
- עלולים אין לשמש סדרקציות להב מסור או ברגרם אם הם פגומים או לא מותאיים. דקיקות המסור והברגים תוכנו בוים יחד עבורי המסור שלך, כדי לספק ביציעים ובטיחות מיטביים.
- רתע - סיבות והוראות בטיחות מתחייבות**
- רתע זו תגובה פואומיות כתוצאה מהתיקעות או תכוונה לא טוביה של להב המoso, הגורמת לכך שהמסור מתרומם לא לשילטה וזרק מהחلك שבעבודה החוצה לכיוון האדם המפעיל את המoso;
 - אם החירץ המנורט נסגר ועקב כך להב המoso נתקע, המסור ייחסם וכוח המכוון יזרוק את המoso לכיוון המפעיל;



- אם לאב המטוסור מסתובב בצורה לא טובה בחתון, השינויים של הקצה האחורי של לאב המטוסור עלולות להיתקע בפפי השטה של החלק בעבודה, ועקב זאת לאב המטוסור יונע אל מחוץ לחץ המונוכר והמטוסור יקפוץ לאחריו לכיוון המפעלי.
- רגע נוצר כתוצאה של שימוש שגוי במטוסור. ניתן למונע אותו באמצעות אמצעי הדזרות המוטיברים להלן.
- אחד את המטוסור היבש בשתי ידיים והזקק את דזוטוקן בתנופה שבה יכול לסייעו את כוחות הרתען. עםוד תמייד באצ' לאב המטוסור, לעולם אל תביא את המטוסור לכאן אחד עם הגוף שלו. במקרה של רתען המטוסור העגול עשוי לקפוץ לאחרו, אולם המפעלי עוזר יכול לשולט בכוחות הרתען אם יקוטר את אמצעי הדזרות המתאים.
- במקרה שהמטוסור נתקע או שאחורה מפטיק לעובד, כבה את המטוסור מהחלה שבעובודה עד שהלאב המטוסור עצם. אל תנסה לשם אופן להרחש רתען. ברור את הסיבה להיתקענות של לאב המטוסור וטפל בעבירות.
- מסתובב. אם תרצה לפעיל מחדש מטוסור שתתקע בחולק שבעובודה, עילך לרוכד את לאב המטוסור בחזרץ המונוכר ולוזוד ששיין הלabay אין תקונות בחלק. אם לאב המטוסור יתקע הוא עלול לנען אל מחוץ לחולק שבעובודה או לגרום להרענה כתפעיל חדש את המטוסור.
- לפני ניסורו לוחות גדולים יש לתמוך אותם מלמטה, כדי למנוע רתען עקב היתקענות של לאב המטוסור. לוחות גדולים עשויים לתוכנוף תחת משקלם העצמי. יש לתמוך לוחות גדולים מלמטה משבי צדיהם, גם בקרבת החירץ המונוכר וגם בקצתם.
- אל תשמש בהגביה מטוסור כהיים או פגומים. להבי מטוסור פגומים או בעלי שיבים לא מתאימים יסרו חירץ צר פדי, שיגרום לחיכוך מוגבר, להיתקענות לאב המטוסור ולrutען.
- יש לקבע את עומק החיתוך וחווית החיתוך לפני תחילת העבודה ולהדק היטב. אם הכוונונים האלה ישתנו במהלך הניסוי עלול להיתקע ולגרום לרתען.
- היה זהり במתיחות ובביסטרו קיימים או חלקים דומים. כאשר לאב המטוסור חודר פנימה הוא עשוי לעדי עצמים מושתטים ולגרום לרתען.

נקודות מגן להלב התחתון

- בדוק לפני כל שימוש אם מגן להלב התחתון נסגר ב佐ורה חלקה. אל תשמש במטוסור אם מגן להלב התחתון איינו בעחותפות ואינו נסגר מידי. לעולם אין לקשו או לתפoso את מגן להלב התחתון במצב פתוח. אם המטוסור ייפול לרצפה מגן להלב התחתון עלול להתקען. פתח את המגן באפשרויות ידיית המשיכה והוא שעוזר בעחותפות, ושבכל דזיות ועומקי החיתוך הוא אכן נוגע בהגביה המטוסור או בחלקים אחרים.
- בדוק את תפקוד הקפץ של מגן להלב התחתון. אם מגן להלב התחתון והקפץ אינם פועלים באופן מושלם דאג לתיקונם לפני תחילת העבודה. חלקים פגומים, משקעים ובקרים או יצטברויות של בסותות ישבשו את פעולת מגן להלב התחתון.
- פתח את מגן להלב התחתון ב传达ות ידיך ורק לצורך ביצוע חיתוכים כגון חיתוכים בחדרה וחיתוכים בזויה.فتح את מגן להלב התחתון ב传达ות ידי המשיכה לאחור ואדי שחרר את הדיתרי ברגע שהמטוסור חודר לחולק שבעובודה. בכל בעותות הניסוי האחרות אמור מגן להלב התחתון לפעול באופן אוטומטי.
- אל תכini את המטוסור על שולחן העבודה או על הקרקע לפני שלב המטוסור כוסה על ידי מגן להלב התחתון. לאב מטוסור לא מונע שעדין לא עציר ידוחף את המטוסור בגדי כוון החירוץ יונסרו את כל מה שיימצא בדרך. שים לב שהמטוסור ממשיך להסתובב מעט גם לאחר סיום העבודה.


2.3 הנחיות בטיחות נוספות למטוסרים עגולים

- הולך את המטוסור העגול הידני רק כשהוא מופעל נגד החלק שבעובודה.
- ↔ מסלול החיתוך צריך להיות פניו ממכתלים מלמעלה ולמטה. אין לנסר ברגים, מסמרים וכדומה. לעולם אין לעלובוד עם המטוסור מל' הראש.
- אין לבלום את המטוסור על ידי הטטייתו הצדה. מנע התהממות יתר של חזוי השינויים של ההלב. בעת חיתוך פלטטי יש למנוע התכה של הפלטטי.
- השתמש תמיד בדיסק המטוסר המתאים לחומר שבעונתך לבסра.
- השימוש אך ורק בדיסקי מטוסר שהומלכו על ידי Hilti ווננים על דרישות התקן EN 847-1.



3.1 סקירת המוצר 1

- מוליך מקבילי דרוע אחדת **①**
 כוונון דוית החיתוך **②**
 כפחתור חסימת ציר **③**
 דית Achida נוספת **④**
 מותג הפעלה/כיבוי **⑤**
 לחץ חסימת הפעלה **⑥**
 דית Achida **⑦**
 כל חשמל **⑧**
 מנוף נעילת עומק חיתוך **⑨**
 מפתח אלון **⑩**
 לוחית בסיסי קטנה **⑪**
 תארות **⑫**
 מנוף נעילה למוליך המקבילי מלפנים **⑬**
 מנוף נעילת דוית חיתוך **⑭**
 סקלאלת עומק חיתוך **⑮**
 מוחבר שאיבת אבק **⑯**
 מגן דיסק **⑰**
 מנוף לתפעול מגן הלהב והקפיyi **⑱**
 מנוף נעילת המוביל המקבילי מאחוריו (רק עבור לוחית בסיס גודלה) **⑲**
 מגן דיסק קפפי **⑳**
 ציר העגלה **㉑**
 חז כיוון סיבוב **㉒**
 מוליך מקבילי שתי דראעות **㉓**
 סימונו חרט 0° **㉔**
 סימונו חרט 45° **㉕**
 סקלאלת דוית חיתוך **㉖**
 לוחית בסיס גודלה **㉗**
 בורג הרזק **㉘**
 אוגן בגדי **㉙**
 אוגן בסיס **㉚**
 חריץ סימנו 0° לוחית בסיס **㉛**
 סימונו חרץ $1^\circ - 50^\circ$ לוחית בסיס **㉜**

**3.2 סקירת מתאם סרגל ההולכה 2**

- חרץ סימנו 0° **㉓**
 סימנו חרץ $1^\circ - 50^\circ$ **㉔**

- דדים אחרים **㉕**
 דוד קדרני **㉖**

3.3 שימוש בהתאם ליעוד

המוצר המתואר הוא מסור עגול. הוא מיועד לעבודות ניסור בעץ או בחומרים דומים, בפלסטיקים, בקרטון גבס, בלוחות גבס ובחומרים מודכבים, עד לעומק חיתוך של 55 מ"מ וכן לחיפויים אלכסוניים בהזווית של עד 50° .

3.3.1 שימוש שגוי אפשרי

אסור להשתמש בדיסקי מסור שאינם תואימים את המפרט הטכני הדרושים, בדיסקי חיתוך, בדיסקי השחזה וכן בדיסקי מסור מפלחת HSS. אין לסרור מתקנות.

3.4 מפרט אספקה

מסור עגול, להב מסור, מפתח אלון, מוליך מקבילי, הוראות הפעלה.



לצורך הפעלה בטוחה של המכשיר יש להשתמש רק בחלקי חילוף וחומרים מתאימים מקוריים. את חלקי החילוף, החומריים המתקלים והאביזרים שאושרו על-ידינו עבור המוצר שולק תמצאו ב-**Hilti Store** של Hilti או בכתובת: www.hilti.group



4 נתוני טכניים

4.1 נתונים טכניים

את המידע הנקוב, הדרם הנקוב, התדריות וההספק הנקוב תמצא בלוחית הדגם הספציפית למדינתך.



בעת הפעלה באמצעות גברטו או שבאי הספק המוצע שלהם חייב להיות לפחות כפול מהספק הנקוב הנוכחי על לחות הדגם של המכשיר. מתח העבודה של השאבי או הגברטו חייב להיות תמיד לפחות 5% + בין 15%- 20% - ביחס למתח הנקוב של המכשיר.

משקל, לוחית בסיס קטנה	ק"ג 4.5
משקל, לוחית בסיס גדולה	ק"ג 4.7
קוטר דיסק מסור	מ"מ ... 165 מ"מ
עובי דיסק של להב המסתור	מ"מ ... 1.5 מ"מ
קוח חיבור של דיסק המסתור	מ"מ 20
עומק חיתוך ב-0°	מ"מ ... 55 מ"מ
עומק חיתוך ב-45°	מ"מ ... 41 מ"מ
עומק חיתוך ב-50°	מ"מ ... 37 מ"מ
מהירות סיבוב סרק	ס"ד 5,500

4.2 ערכי רעש לפי EN 62841

ערכי לחץ הקול והרעידות המציגים בהוראות אלה נמדדו בהתאם לנוהל המדידה התקני, וניתן להשתמש בהם לצורך השוואתם בין כל עבודה צחמלית. הם מותאמים גם להערכת דמיית של העומסים.

הנתונים הציגים להיפך לשימושים העיקריים בכל הפעולות החשיטלי. אולם אם משתמשים בכל הפעולות לשימושים אחרים, למשל אבידים אחרים או אם המכשיר אינו עבר תחזוקה מספקת, הנתונים עשויים לשינויים. בעקבות זאת פרישת העומסים למשך זמן רב יכולה כולן לשינוי להיראות האזורה באופן משמעותי.

לצורך הערכה חדוקית של העומסים יש ללקחת בחשבון גם את הדפוסים שבהם המכשיר מבוטה או שבתוכם הוא פועל אך אכן בשימוש בפועל. בעקבות זאת פרישת העומסים למשך זמן רב יכולה לשינוי להיראות במוכחה באופן משמעותי. יש לקבע הנחיות בטיחות נוספות להגנה על המסתור של קול / או רuidות, כגון: מחזקה של כל הפעולה החשמלי ושל כל הפעולה המוחדרים, שמירה על ידיים חממות, ארגון תהליכי העבודה.

מידע על רעשין

רמת הספק קול (L _{WA})	101 dB(A)
幡לץ לחץ קול (L _{PA})	90 dB(A)
אי זדאות	3 dB(A)

מידע על רuidות

ערך רuidות מרוחבי בניסור עץ (a _h)	ולט 230 וולט 110 וולט 110
(a _h)	ק"מ/ ² שט' ² 2.12 ק"מ/ ² שט' ² 1.77 רג/ ² שט' ² (6.96) 5.81 רג/ ² שט' ²
אי זדאות (K)	מ"מ/ ² שט' ² 1.5

5 תפעול

5.1 הסרת דיסק המסתור



סכת כויה סכנה עקב התהלהות הכל', האגן או הבוגר והקצוות החדשים של להב המסתור.

השימוש בכפפות מגן כשאתה מוחלף כל'.

1. נתק את תקע החשמל משקע רשת החשמל.
2. הכנס את המפתח אל לבוגר ההידוק של להב המסתור.



2112861

עברית 17

3. לחץ על כפתור חסימת הציר והזקק אותו לחוץ.
4. סובב את בורג ההיידוק של להב המטדור בעדרת מפתחת האלון עד שכפתור חסימת הציר נגען לגמורי.
5. סובב את בורג ההיידוק בעדרת מפתחת האלון כך ציוויל השגור כדי לשחרר את הבורה.
6. הואית את בורג ההיידוק ואית האוגן הנגדי החיצוני.
7. פתח את מגן להב הקפיצי והסר את להב המטדור.

במקרה הצורך ניתן להסיט את אוניברסיטת הבסיס לצורך ניקוי.



5.2 התקנת דיסק מסור ▶

הירוח ▲

- סכנת בדק נלבבי מטדור לא מטאימים או שחוברו שלא כהילה עלולים לגרום לך למטדור.
- ◀ השתמש רק בללבבי מטדור המטאימים למטרות זה. שים לב לפחות ציוויל הסיבור על להב המטדור.
 - ◀ השתמש רק בדיסקי מסור שמהירות הסיבור המוטורת שלהם גבוהה כמו זו הרווחת הסיבור המרכיבת על המטדור.

1. נתקן את תקע החשמל משאע רשת החשמל.
2. נקיה את אוניברסיטת הבסיס ואית האוגן הנגדי.
3. לחבר את אוניברסיטת הבסיס בצדון הנכון.
4. פחח את מגן הדיסק הקפיצי.
5. כבר להב מסור חדש.
6. לחבר את האוגן הנגדי בצדון הנכון.
7. לחבר את בורג ההיידוק.
8. הכנס את מפתחת האלון לבורג ההיידוק של להב המטדור.
9. הדק את האוגן הנגדי בעדרת הבורג על ידי סיבובי בכיוון השעון. החדק תוך כדי אחת את כפתור חסימת הציר לחוץ.
10. לפני הפעלתה המטדור ואית להב המטדור ישוב היטב וכוכן.

5.3 כוונון עומק החיתוך 5

1. נתקן את תקע החשמל משאע רשת החשמל.
 2. שחרר את מנוף הכעילה של כוונון עומק החיתוך.
 3. הרם את המטדור העגול בתנועת מספריים וקבע את עומק החיתוך.
- ↔ עומק החיתוך ייזג על סקלאלת עומק החיתוך.

כדי להשיג חיתוך נקי, עומק החיתוך צריך להיות גדול ב-2 מ"מ מעובי החומר.



4. קבע את מנוף הכעילה של כוונון עומק החיתוך.

5.4 כוונון דזיות החיתוך 6

1. נתקן את תקע החשמל משאע רשת החשמל.
 2. שחרר את מנוף הכעילה של כוונון דזיות החיתוך.
 3. הטה את לוחית הבסיס לזרות החיתוך המכובשת.
- ↔ דזיות החיתוך מוצאג על סקלאלת דזיות החיתוך.
4. הדק את מנוף הכעילה של כוונון דזיות החיתוך.

5.5 סמן חיתוך 5.5

בלוחות הבסיס הקדמיות של המטדור העגול ישנות סמן חיתוך גם עבורי חיתוך ישר וגם עבורי חיתוך צוויתי (0° - 45°). כך ניתן לבצע חיתוך מדויק בזרות החיתוך שנבחרה. קצה הסימון מקוביל לצד הפנימי של להב המטדור. בפתח הקדמי עבורי המטדור ישנו סמן חיתוך.

5.5.1 ניטור לפִי סימון ▶

- הדק את החלק שבundayה כך שלא יוכל לדוד ממקומו.
- ארגן את החלק בונזואה כך שדיסק המטדור יוכל לנבע בחופשיות מתחתיו.
ואו שטמת הפעלה/כיבוי של המטדור נמצא במצב באובב כוכן.
- הצב את המטדור העגול עם לוחית הבסיס על החלק שבundayה כך שעדין לא יהיה מגע בין דיסק המטדור לחלק שבundayה.

1. הפעל את המטדור העגול.



2. הולך את המסור העגול בקצב מתאים לאורכו הסימון על פני החלק שבעובודה.

5.6 ניסור בעדרת מוליך מקובל

המוליך המקורי מאפשר חיתוכים מדויקים במקביל לקצה החלק וחיתוך של פסים מדויקים. ניתן להתקין את המוליך המקורי מידי לוחית הבסיסים. המוליך המקורי עם שתי הדרגות אפשרי לשימוש רק עםلوحית הבסיסים הגדולה. בעת התקנת המוליך המקורי יש לשים לב שכיוון התקנה נכון.

5.7 ניסור עם סרגל הולכה.

שימוש בסרגל הולכה בזמן הניסור מפחית את הסיכון לרתעה.

5.7.1 הצבה/הזאהה של המסור העגול בהתאם לסלג הולכה 9

במסויים בעלי לוחית בסיסים קטנה יש להשתמש בהתאם לסלג הולכה סרגל הולכה 9 

1. הסר את המוליך המקורי אם möglich.
2. דחף את לוחית הבסיסים על הדיזים האחוריים של מתחם סרגל הולכה.
3. הכנס את לוחית הבסיסים במלואה מלפנים למתחם סרגל הולכה. לוחית הבסיס צריכה להינצל במלואה מידי הקדמי.
4. להסרה משוו את הדיז הקדמי מעט קדימה והזאהה את המסור העגול בהתאם לסלג הולכה.

5.7.2 חיתובי אורך בזווית 0°

הצב את המסור העגול עם סימון החירץ "0°" על המוט של סרגל הולכה. ▶

5.7.3 חתכי אורך בזווית עד 50°



סכנת בזק הצבת המסור על החירץ הלא נכון תגרום להתגשות של דיסק המסור בסרגל הולכה.
◀ הצב את המסור בחירץ הנכון.

◀ הצב את המסור עם סימון החירץ "1°-50°" על המוט של סרגל הולכה.

5.7.4 ניסור עם סרגל הולכה 12

1. הדק את סרגל הולכה מילא באמצעות שטן כליבות.
2. הצב את המסור העגול בחלק התחתי של סרגל הולכה. עברו חיתומי אורך בזווית חיתוך של 20° – 50° יש לפתח ידנית את מגן הדיסק.

יש להציב את המסור העגול על סרגל הולכה מתחמי החלק שבעובודה.
ואו שאלבו המסור אוינו בוגע בחלק שבעובודה. 

3. הפעל את המסור העגול.
4. דחף את המסור העגול בקצב אחד מעל החלק שבעובודה.
⇨ כשמגן הדיסק נתקל בפינה הקטומה בזווית חיתוך מתחת -20° הוא נפתח אוטומטית.
⇨ הוא נסגר בבדירה ביציאה מסרגל הולכה.

5.8 ניסור עם ולא שאיית שבבים

המסור העגול מוציא במחבר התהבר לצינורות שאיבה טנדורטיים בקוטר של 27 מ"מ. ניתן שתזוזק למתחם כדי לחבר את צינור שאיבת האבק למסור העגול.

השתלט על השימוש תמיד במכשיר בשואב אבק בידי המידיע לעץ או לעץ ולחומרם מינרליים.
אם אתה עובד לא שאית באבק, כוונת את פליטת השבבים כך שהם ינותבו הרחק מפה.

השתמש ככל במסכת נשימה ברמת סיכון P2, ודאג לאוורור מספיק תמיד, כדי להפחית את כמות האבק שאתה גושם. 



טיפול ותחזוקה 6.1

⚠️ אזהרה

סכנת החשמלנות! בעבודות טיפול ותחזוקה כאשר תקע החשמל מוחבר לשען עלולות להוביל לפציעות ולכויות קשות.
▪ לפני ביצוע עבודות טיפול או תחזוקה כלשהו יש להකפיד ולנקת את תקע החשמל!

טיפול

- הסר בדזרות לכלוּך שנדבק.
- נקה בדזרות את חריצי האוורור באמצעות מרשת יבשה.
- נקה את גוף המכשיר רק בעדרת מטלית לחאה מעט. אין להשתמש בחומר טיפול המכילים סיליקון, מאחר שהם עלולים פגוע בחלקה הפלטטי.

תחזוקה

⚠️ אזהרה

סכנת החשמלנות! תיקו לא מקצועי של רכיבים شمالיים עלול לגרום לפציעות קשות ולכויות.
▪ רק شمالיים מורשים רשאים לבצע תיקונים ברכיבים חמליים.

- יש לבדוק באופן סידר את כל החלקים הגלויים כדי לאטר נקדים ולודא שככל הרכיבים פועלים באופן תקין.
- אם ישם נקדים / או תקלות אין להפעיל את המוצר. הבא מיד את המכשיר לתיקון במ官方微博 שירות של **Hilti**.
- לאחר לבצע עבודות טיפול ותחזוקה יש להקפיד ולהזכיר את כל התקני ההגנה ולבדק את תפקוד המכשיר.



לצורך הפעלה בטוחה של המכשיר יש להשתמש רק בחלקי חילוף וחומרים מתכליים מקוריים. את חלקי החילוף, החומריים המתכליים והאביזרים שאושרו על-ידיינו עבור המוצר שlk תמצא ב- **Hilti Store** שlk או כתובות: www.hilti.group

6.2 בדיקות לאחר עבודות טיפול ותחזוקה

לאחר ביצוע עבודות טיפול ותחזוקה יש לבדוק שכל התקני ההגנה מותקנים ופועלים ללא תקלות.



- כדי לבדוק את מגן הדיסק הקפיצי פתח את המגן עד הסוף באמצעות הידית.
- ↳ שחרר את הידית וודאג ש מגן הדיסק הקפיצי נסגר לגמarity במהירות.

6.3 ניקוי תעלת השבבים

יתקן שתצטרכ לפרק את דיסק המסתור במלל הניקוי.



- נקה את תקע החשמל משקע רשת החשמל.
- הסר את דיסק המסתור. ← עמוד 17
- נקה את תעלת השבבים.
- התקן את דיסק המסתור. ← עמוד 18
- בדוק אם החלקים הנגעים פעילים ב佐ורה חלקה ואינם נתקעים ואם ישנם חלקים שבורים או מוקללים הפשבשים את פעולתה התקינה של המכשיר.

6.4 ניקוי התקני ההגנה

- הסר את דיסק המסתור. ← עמוד 17
- נקה את התקני ההגנה בדזרות בעדרת מרשת יבשה.
- הסר משקעים ושבבים בחלק הפנימי של התקני ההגנה בעדרת כל עבודה מותאים.
- התקן את דיסק המסתור. ← עמוד 18

7 איתור תקלות

תקלה	סיבה אפשרית	פתרון
המכשיר אינו פועל בעוצמה מלאה.	השתמש בכבל מאריך ארוך מדי / או הקווטר שלו בעל קווטר גודל מסוים.	הכבל המאריך ארוך מדי / או הקווטר מותיר או קען מדי.



תקלה	סיבה אפשרית	פתרונות
המckerיר אינו פועל בעוצמה מלאה.	מתוך אפקט החשמל נמוך מדי.	לחבר את המCKERIR למקור מתח אחר.
המckerיר אינו פועל.	אפקט החשמל נזוקה.	לחבר מCKERIR חשמלי אחר ובודק אם הוא פועל.
כבל החשמל או תקע החשמל אינם תקין.	hab'a את כבל החשמל או התקע לבריה, ובמקרה הנזקן לתיקון, אצל Hilti.	hab'a את המCKERIR שולחן תקע או השירות של Hilti כדי לתקן את המOTOR.
מתג הפעלה/כיבוי לא תקין.	פונה לשירות של Hilti כדי לתקן את המOTOR.	פונה לשירות של Hilti כדי לתקן את המOTOR.
אין שאיבת החלהשה מודול.	תקעת השבכים סתומה.	נקה את תעלת השבכים. ← עמוד 20
מגן הדיסק הקפיצי אינו נסגר.	תקע ההגנה סתום.	נקה את התקע ההגנה. ← עמוד 20
המCKERIR רודע יותר מהרגיל.	דיסק המסגור מותקן באופן שגוי.	הסר את דיסק המסגור והתקן אותו מחדש נכונה.

8 סילוק

המCKERIR של Hilti מיוצרים בחלקם הגדל מחומרים ניטנים למיחוזר. כדי שニיטן יהיה למחוזר דרושה הפרדת חומרים מקצועית. במידונות ובוות Hilti מקבל את המCKERIR הישן שרך בחרדר לצורכי פיזיוזו. פונה לשירות של Hilti או למשווק.

◀ אין להשליך כל' עובדה חשמליים, כלים אלקטרוניים וסוללות לפסולות הביתיית! 

9 RoHS (תקנה להגבלת השימוש בחומרים מסוכנים)

בקישור הבא תמצוא את טבלת החומרים המסוכנים: qr.hilti.com/r2937786 QR. קישור לטבלה RoHS תמצא בסוף ייעוד זה, בצדota קוד QR.

10 אחוריות יצרן

◀ אם יש לך שאלות בנוגע תאבי האחוריות, פונה למשווק Hilti הקרוב אליו.







Hilti Corporation
Feldkircherstraße 100
9494 Schaan | Liechtenstein

SC 55W (01)

[2015]

2006/42/EC

EN 55014-1 :2017

2014/30/EU

EN 55014-2:2015

2011/65/EU

EN 62841-1

EN 61000-3-2:2019

EN 62841-2-5

EN 61000-3-11 :2019

Schaan, 17.06.2020

Paolo Luccini

Head of Quality and Process Management
BA Electric Tools & Accessories

Tassilo Deinzer

Executive Vice President
Business Unit Power Tools & Accessories



SC 55W



Hilti Corporation

L1-9494 Schaan

Tel.: +423 234 21 11

Fax: +423 234 29 65

www.hilti.group



2112861